

# IOAHMP Annual Updates 2024

|                                 | Club |                        | Gate |                       | Pipe      |             | Longitude (X) | Latitude (Y) | Description                                                                                                          | IOAHMP Update                                                       |
|---------------------------------|------|------------------------|------|-----------------------|-----------|-------------|---------------|--------------|----------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|
| Update                          | No.  | Name                   | ID   | Interior/<br>Exterior | Dia. (in) | Length (ft) |               |              |                                                                                                                      |                                                                     |
| Replaced Existing Structures    | 105  | Sweetwater Gun Club    | b    | Int.                  | 36        | 40          | -122.125510   | 38.208709    | Replace/upgrade 36" HDPE Flashboard Riser                                                                            | Infrastructure table                                                |
|                                 | 105  | Sweetwater Gun Club    | c    | Int.                  | 36        | 40          | -122.119606   | 38.210976    | Replace/upgrade 36" HDPE Flashboard Riser                                                                            | Infrastructure table                                                |
|                                 | 105  | Sweetwater Gun Club    | d    | Int.                  | 36        | 40          | -122.118912   | 38.204130    | Replace/upgrade 36" HDPE Flashboard Riser                                                                            | Infrastructure table                                                |
|                                 | 105  | Sweetwater Gun Club    | e    | Int.                  | 36        | 40          | -122.119485   | 38.211031    | Replace/upgrade 36" HDPE Flashboard Riser                                                                            | Infrastructure table                                                |
|                                 | 123  | Walnut Creek Gun Club  | G    | Ext.                  | 24        | 40          | -122.054801   | 38.211464    | Replaced Stainless Steel Screw Gate                                                                                  | Infrastructure table                                                |
|                                 | 124  | Fat Hen Farm           | B    | Ext.                  | 36        | 40          | -122.051738   | 38.198371    | Replaced with Stainless Steel Screw Flap                                                                             | Infrastructure table                                                |
|                                 | 331  | Tonnesen Ranch         | a    | Int.                  | 24        | 40          | -121.899732   | 38.187729    | Replaced HDPE Pipe                                                                                                   | Infrastructure table                                                |
|                                 | 331  | Tonnesen Ranch         | b    | Int.                  | 18        | 40          | -121.900691   | 38.191097    | Replaced HDPE Pipe and FBR                                                                                           | Infrastructure table                                                |
|                                 | 331  | Tonnesen Ranch         | c    | Int.                  | 24        | 40          | -121.900384   | 38.191178    | Replaced HDPE Pipe and FBR                                                                                           | Infrastructure table                                                |
|                                 | 401  | PFC - Gold Hill        | A    | Ext.                  | 36        | 40          | -122.129487   | 38.184013    | Replaced interior/exterior combo gates                                                                               | Infrastructure table                                                |
|                                 | 402  | PFC - Golden Gate      | A    | Ext.                  | 24        | 50          | -122.125700   | 38.178938    | Replaced interior FBR and exterior SS flap                                                                           | Infrastructure table                                                |
|                                 | 403  | PFC Garibaldi          | E    | Ext.                  | 30        | 50          | -122.109129   | 38.162409    | Replaced exterior combo gate                                                                                         | Infrastructure table                                                |
|                                 | 410  | Gibson Horseshoe       | E    | Ext.                  | 36        | 40          | -122.097680   | 38.161512    | Replaced SS exterior flap gate                                                                                       | Infrastructure table                                                |
|                                 | 425  | California Farms       | FS   | Ext.                  | 24        | 55          | -122.049849   | 38.153280    | Replaced 8" Fish Screen and Fish Screen Base Platform, New bulkhead, 30" HDPE pipe, SS ext. canal gate, & SS int. FG | Infrastructure table                                                |
|                                 | 505  | Dead Duck              | E    | Ext.                  | 36        | 50          | -122.018503   | 38.170452    | Replaced SS combo gate                                                                                               | Infrastructure table                                                |
|                                 | 505  | Dead Duck              | F    | Ext.                  | 36        | 50          | -122.018054   | 38.170770    | Replaced 36" HDPE pipe & SS ext. FG                                                                                  | Infrastructure table                                                |
|                                 | 506  | Four Winds             | FS   | Ext.                  | 24        | 55          | -122.017630   | 38.171215    | Replaced 30" HDPE pipe, ext. SS canal gate, int. SS FG                                                               | Infrastructure table                                                |
|                                 | 526  | Flatlander             | A    | Ext.                  | 36        | 55          | -121.957288   | 38.185043    | Replaced with HDPE pipe & SS SG                                                                                      | Infrastructure table                                                |
|                                 | 601  | Can Can                | A    | Ext.                  | 36        | 40          | -121.942595   | 38.177792    | Replaced Stainless Steel Screw Gate                                                                                  | Infrastructure table                                                |
|                                 | 621  | Stone Duck             | i    | Int.                  | 36        | 20          | -121.939057   | 38.131257    | Replaced 36" HDPE pipe 20ft.                                                                                         | Infrastructure table                                                |
|                                 | 621  | Stone Duck             | tt   | Int.                  | 36        | 20          | -121.944867   | 38.135815    | Replaced 36" HDPE pipe 20ft.                                                                                         | Infrastructure table                                                |
|                                 | 621  | Stone Duck             | uu   | Int.                  | 36        | 20          | -121.942791   | 38.134226    | Replaced 36" HDPE pipe 20ft.                                                                                         | Infrastructure table                                                |
|                                 | 621  | Stone Duck             | vv   | Int.                  | 36        | 20          | -121.940177   | 38.132128    | Replaced 36" HDPE pipe 20ft.                                                                                         | Infrastructure table                                                |
|                                 | 625  | Pintail Ranch          | A    | Ext.                  | 36        | 50          | -121.919152   | 38.148103    | Replaced 36" - 50 ft. HDPE pipe, ext. SS FG, int. open                                                               | Infrastructure table                                                |
|                                 | 625  | Pintail Ranch          | u    | Int.                  | 36        | 20          | -121.930124   | 38.140549    | Replaced 36" - 20ft HDPE pipe, int & ext open                                                                        | Infrastructure table                                                |
|                                 | 631  | Meins Landing          | C    | Ext.                  | 24        | --          | -121.914362   | 38.125499    | Replace 24" ext. SS/FG and int. FBR                                                                                  | Infrastructure table                                                |
|                                 | 631  | Meins Landing          | D    | Ext.                  | 24        | --          | -121.909221   | 38.119809    | Replace 24" HDPE pipe and SS combo gates (work completed in Aug 2023)                                                | Infrastructure table                                                |
|                                 | 631  | Meins Landing          | +    | Ext.                  | 20        | 80          | -121.909009   | 38.138709    | Pump pipe replacement with 20" - 80 ft. HDPE pipe, ext. SS FG                                                        | Infrastructure table                                                |
|                                 | 703  | The Friendly Godfather | A    | Ext.                  | 36        | 50          | -122.075182   | 38.119884    | Replaced ext. SS combo gate                                                                                          | Infrastructure table                                                |
|                                 | 703  | The Friendly Godfather | c    | Int.                  | 36        | 30          | -122.067207   | 38.113689    | Replaced 36" HDPE pipe and 36" canal gate                                                                            | Infrastructure table                                                |
|                                 | 804  | Sprig Farm             | e    | Int.                  | 36        | 40          | -121.964257   | 38.106517    | Replaced Stainless Steel Screw Gate                                                                                  | Infrastructure table                                                |
|                                 | 907  | River Dog Resort, LLC  | a    | Int.                  | 36        | 40          | -121.905536   | 38.085797    | Replaced Stainless Steel Screw Gate                                                                                  | Infrastructure table                                                |
| Installed New Structure         | 612  | Meridian Gun Club      | c    | Int.                  | 24        | 50          | -121.941067   | 38.145282    | Installed new 24" - 50 ft. HDPE pipe, ext. SS/SG, int. open                                                          | IMP Section B.2, Infrastructure table, NAIP Map, Infrastructure Map |
|                                 | 625  | Pintail Ranch          | xx   | Int                   | 24        | 30          | -121.918799   | 38.147880    | Installed new 24" - 30 ft HDPE pipe, FBR ext., int. open                                                             | Infrastructure table, NAIP Map, Infrastructure Map                  |
|                                 | 802  | Rich Island Gun Club   | G    | Ext.                  | 36        | 55          | -121.985068   | 38.085394    | Installed new gate                                                                                                   | Infrastructure table, NAIP Map, Infrastructure Map                  |
|                                 | 807  | Wheeler Island         | C    | Ext.                  | 36        | 55          | -121.960392   | 38.080609    | Installed new gate, included bulkhead                                                                                | Infrastructure table, NAIP Map, Infrastructure Map                  |
|                                 | 807  | Wheeler Island         | D    | Ext.                  | 36        | 55          | -121.960232   | 38.080643    | Installed new gate, included bulkhead                                                                                | Infrastructure table, NAIP Map, Infrastructure Map                  |
|                                 | 807  | Wheeler Island         | E    | Ext.                  | 36        | 55          | -121.960232   | 38.080643    | Installed new gate, included bulkhead                                                                                | Infrastructure table, NAIP Map, Infrastructure Map                  |
|                                 | 807  | Wheeler Island         | F    | Ext.                  | 36        | 55          | -121.957821   | 38.080180    | Installed new gate, included bulkhead                                                                                | Infrastructure table, NAIP Map, Infrastructure Map                  |
|                                 | 623  | Frost Slough           | --   | --                    | --        | --          | --            | --           | Moved blind locations                                                                                                | NAIP Map, Infrastructure Map, Elevation Map                         |
| Corrections to Certified IOAHMP | 129  | Grizzly Bay Preserve   | --   | --                    | --        | --          | --            | --           | RD 2034 Dissolved                                                                                                    | IMP Section B.4                                                     |
|                                 | 304  | Denverton Land Co.     | --   | --                    | --        | --          | --            | --           | RD 2134 Dissolved                                                                                                    | IMP Section B.4                                                     |
|                                 | 305  | Marianno Ranch         | --   | --                    | --        | --          | --            | --           | RD 2134 Dissolved                                                                                                    | IMP Section B.4                                                     |
|                                 | 423  | The Family Gun Club    | --   | --                    | --        | --          | --            | --           | Addition of 4.04 acres managed wetland area                                                                          | IMP Section B                                                       |
|                                 | 907  | River Dog Resort, LLC  | --   | --                    | --        | --          | --            | --           | Club name change on IMP                                                                                              | IMP All Sections                                                    |
|                                 | 932  | Concord Farms          | f    | Int.                  | 30        | 20          | -121.873602   | 38.068684    | Correction to 30" pipe and arrow direction on maps                                                                   | Infrastructure table, NAIP Map, Infrastructure Map                  |
|                                 | 932  | Concord Farms          | h    | Int.                  | 24        | 20          | -121.871978   | 38.066013    | Correction to 24" pipe                                                                                               | Infrastructure table                                                |
|                                 | 932  | Concord Farms          | k    | Int.                  | 24        | 20          | -121.873426   | 38.066228    | Correction to show relocation of water structure and pipe                                                            | Infrastructure table, NAIP map, Infrastructure map                  |
| Update to Map                   | 130  | Track Pond             | --   | --                    | --        | --          | --            | --           | New Interior Ditch (2,400 linear feet)                                                                               | Infrastructure Map                                                  |
|                                 | 612  | Meridian Gun Club      | B    | Ext.                  | --        | --          | -121.919215   | 38.148289    | Shared Gate Removed                                                                                                  | Infrastructure table, NAIP Map, Infrastructure Map, Elevation Map   |

# IOAHMP Annual Updates 2024

|                                                           |     |                |    |      |    |    |             |           |                                                                                                                                                                                                                                                                      |                                                                                    |
|-----------------------------------------------------------|-----|----------------|----|------|----|----|-------------|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|
| Update Due to Shared Water Level/Water Control Structures | 618 | Hidden Cove    | B  | Ext. | -- | -- | -121.919215 | 38.148289 | Shared Gate Removed                                                                                                                                                                                                                                                  | IMP Section B.2, Infrastructure table, NAIP Map, Infrastructure Map, Elevation Map |
|                                                           | 619 | Schafer Farms  | -- | --   | -- | -- | --          | --        | Club #621 replaced structures "i, tt, uu, vv" with 36" HDPE pipe; Club #625 replaced structure A with 36" HDPE pipe, ext. SS FG; Club #625 replaced structure u with 36" 20ft HDPE pipe, Club #625 installed new interior gate "xx" with 24" HDPE pipe and ext. FBR. | Infrastructure table; Infrastructure Map                                           |
|                                                           | 621 | Stone Duck     | -- | --   | -- | -- | --          | --        | Club #625 replaced structure A with 36" HDPE pipe, ext. SS FG; Club #625 replaced structure u with 36" 20ft HDPE pipe, Club #625 installed new interior gate "xx" with 24" HDPE pipe and ext. FBR.                                                                   | Infrastructure table; Infrastructure Map                                           |
|                                                           | 623 | Frost Slough   | -- | --   | -- | -- | --          | --        | Club #621 replaced structures "i, tt, uu, vv" with 36" HDPE pipe; Club #625 replaced structure A with 36" HDPE pipe, ext. SS FG; Club #625 replaced structure u with 36" 20ft HDPE pipe, Club #625 installed new interior gate "xx" with 24" HDPE pipe and ext. FBR. | Infrastructure table; Infrastructure Map                                           |
|                                                           | 625 | Pintail Ranch  | -- | --   | -- | -- | --          | --        | Club #621 replaced structures "i, tt, uu, vv" with 36" HDPE pipe                                                                                                                                                                                                     | Infrastructure table; Infrastructure Map                                           |
|                                                           | 632 | Sheriff Pond   | -- | --   | -- | -- | --          | --        | Club #621 replaced structures "i, tt, uu, vv" with 36" HDPE pipe; Club #625 replaced structure A with 36" HDPE pipe, ext. SS FG; Club #625 replaced structure u with 36" 20ft HDPE pipe, Club #625 installed new interior gate "xx" with 24" HDPE pipe and ext. FBR. | Infrastructure table; Infrastructure Map                                           |
|                                                           | 633 | Boles Pond     | -- | --   | -- | -- | --          | --        | Club #621 replaced structures "i, tt, uu, vv" with 36" HDPE pipe; Club #625 replaced structure A with 36" HDPE pipe, ext. SS FG; Club #625 replaced structure u with 36" 20ft HDPE pipe, Club #625 installed new interior gate "xx" with 24" HDPE pipe and ext. FBR. | Infrastructure table; Infrastructure Map                                           |
|                                                           | 634 | Grizzly Hilton | -- | --   | -- | -- | --          | --        | Club #621 replaced structures "i, tt, uu, vv" with 36" HDPE pipe; Club #625 replaced structure A with 36" HDPE pipe, ext. SS FG; Club #625 replaced structure u with 36" 20ft HDPE pipe, Club #625 installed new interior gate "xx" with 24" HDPE pipe and ext. FBR. | Infrastructure table; Infrastructure Map                                           |

Total Clubs

34