

#### **Directors**

Tony Vaccarella, President Terry Connolly Mike Lewis Jim Waters

#### **Associate Directors**

Dennis Becker **Kurt Black** John Eudy H. Kent Hansen Lalo Kwiat Steve Roerden John Telfer Dick Vanderkous

#### Staff

Steven Chappell **Executive Director** John Takekawa, PhD **Operations Manager** Kelli Perez Office Supervisor Tim Edmunds Water Manager/Biologist Jeff Taylor Water Manager/Biologist Marina Guzman

Water Manager/Biologist Jesirae Collins

**Biologist** 

Jason Hagani **Biologist Analyst** Marque Mouton

LJI Resident Caretaker

### SUISUN RESOURCE **CONSERVATION DISTRICT**

2544 Grizzly Island Road Suisun City, CA 94585-9539 (707) 425-9302

## **AGENDA**

# SUISUN RESOURCE CONSERVATION DISTRICT

**Board of Directors Meeting** Wednesday, May 10, 2023 @ 2:00 PM Solano County Board of Supervisors Chambers 675 Texas Street, Fairfield, CA 94533

- 1. Call to Order ~
- 2. Public Comments ~
- 3. Open Session ~
  - a) Approval of the April 12, 2023, Board Meeting Minutes
- 4. Financial Reports ~
  - a) Approval of the Vendor Claims for April 2023
  - b) Board Approval of Draft the FY 21/22 SRCD Audit
- 5. Department of Fish & Wildlife Report ~
- 6. Department of Water Resources Report ~
- 7. Conduct a Public Hearing in accordance with 14 CCR 11210 to consider a Minor Amendment to the SRCD Local Protection Program updating 34 Individual Ownership **Adaptive Habitat Management Plans and SRCD Board** Resolution 2223-3.

**Attachments:** 

- A) IOAHMP's Annual Updates 2021 & 2022 Summary
- B) CEQA Notice of Exemption
- 8. Suisun Resource Conservation District Reports ~
- a) 2015 SMPA ~ 2023 Drought Response Program Funding Allocation
- b) 2023 PAI Program Update
- c) Suisun Marsh Plan Update
- d) USACE Permits RGP 3 & LOP Update
- e) Water Manager Program Update
- f) Lower Joice Island Update
- g) Summary of Past & Future Meetings, Tours, and Presentations
- 9. SRCD Committee Reports ~
- a) Agency Committee
- b) Legal Committee
- c) Personnel Committee
- d) Finance Committee
- e) Associate Director's Committee
- 10. Adjourn ~

# **IOAHMP Annual Updates 2021**

	Club		Gate		Pipe				
				Interior/					
Update	No.	Name	ID	Exterior	Dia. (in)	Length (ft)	Description	IOAHMP Update	
	40.						Replaced Gate & Pipe with 36" Stainless Steel Exterior Flap		
	405	Sunrise Island	В	Ext	36	50	Gate 50' HDPE Pipe	Infrastructure table	
							Replaced Gate & Pipe with 36" Stainless Steel Exterior Flap		
	405	Sunrise Island	D	Ext	36	50	Gate 50' HDPE Pipe	Infrastructure table	
	414	Drake Sprig	В	Ext	36	-	Replaced Gate with 36" Stainless Steel Exterior Flap Gate	Infrastructure table	
	415	Arnold Ranch	В	Int	36	-	Replaced Gate with 36" Stainless Steel Interior Screw/Flap	Infrastructure table	
	415	Arnold Ranch	С	Int	36	-	Replaced Gate with 36" Stainless Steel Interior Screw/Flap	Infrastructure table	
							Replaced Gates with 24" Stainless Steel Exterior Flap/Interior		
Replaced	415	Arnold Ranch	D	Both	24	-	FBR	Infrastructure table	
Existing							Replaced Gate & Pipe with 30" HDPE FBR / open pipe north		
Structures	415	Arnold Ranch	b	Int	24	40	side of levee	Infrastructure table	
Structures							Replaced Gate & Pipe with 30" HDPE FBR / open pipe north		
	415	Arnold Ranch	С	Int	24	40	side of levee	Infrastructure table	
							Replaced Gate & Pipe with 30" HDPE FBR / open pipe north		
	415	Arnold Ranch	g	Int	24	40	side of levee	Infrastructure table	
							Replaced Gate & Pipe with 30" HDPE FBR / open pipe north		
	415	Arnold Ranch	h	Int	24	40	side of levee	Infrastructure table	
	423	Family Club	D	Ext	36	-		Infrastructure table	
	514	Tree Slough Farms	Α	Ext	36	50	Replaced Gate with ext. with Stainless Steel flap	Infrastructure table	
	514	Tree Slough Farms	С	Ext	36	50	Replaced Gate with ext. with Stainless Steel combo	Infrastructure table	
								IMP section B.2,	
								Infrastructure table,	
								NAIP map, &	
	415	Arnold Ranch	E	Both	24	50	Exterior, SS interior flap gate	Infrastructure map	
Installed								IMP section B.2,	
New								Infrastructure table,	
Structures								NAIP map, &	
Structures	415	Arnold Ranch	F	Both	30	50	SS interior FBR	Infrastructure map	
								IMP section B.2,	
								Infrastructure table,	
							Installed NEW drain gate, - 36" Ext - Stainless Steel flap, Int.		
	514	Tree Slough Farms	D	Ext	36	50	- FBR	Infrastructure map	
Moved Existing Structures								NAIP map,	
								Infrastructure map, &	
	625	Pintail ranch					Moved blind #14 "Polaris"	LIDAR map	
								NAIP map,	
							Relocated blind #2 (existing double blind) to blind #6	Infrastructure map, &	
	632	Sheriff's pond					(existing double blind). Blind #6 relabeled as blind #2	LIDAR map	

**Total Clubs** 

7

Club Gate					Pi	pe				
Update	No.	Name	ID	Interior/ Exterior	Dia. (in)		Longitude (X)	Latitude (Y)	Description	IOAHMP Update
	133	Shelldrake	D	Ext	36	-	-122.054059	38.199922	Replaced Gate with 36" exterior Stainless Screw/Flap	Infrastructure table
	302	Pickleweed Ponds	A	Exterior	24	40	-121.931038		Replaced Existing CMP Pipe with HDPE	Infrastructure table
	304	Denverton	E	Exterior			-121.920210		Replaced 20' bulkhead	Infrastructure table
	318 319	Brass Button Stolte Farm	D	Exterior	36	50 41	-121.927438		Replaced Gate with Stainless Steel Screw Flap	Infrastructure table
	323	Duck & R	A C	Exterior Exterior	36 24	50	-121.927394 -121.910665		Replaced Gate with Stainless Steel Screw Flap Replaced Pipe with HDPE and Gate with Stainless Steel	Infrastructure table Infrastructure table
	405	Sunrise Island	A	Both	24	-	-121.910663		Replaced Int & Ext. Gates (same structures)	Infrastructure table
	405	Sunrise Island	В	Both	36	-	-122.083460		Replaced Int & Ext. Gates (same structures)	Infrastructure table
	406	Teal Club	A	Ext	36	-	-122.079993		Replaced Gate with 36" Stainless Steel Flap	Infrastructure table
Replaced Existing Structures	406	Teal Club	I	Ext	30	-	-122.086365		Replaced Gate with 30" Stainless Screw/Flap	Infrastructure table
	418	Cygnus Gun Club	F	Ext.	24	-	-122.084359		Replaced Gate with 24" Exterior Screw/Flap	Infrastructure table
	418	Cygnus Gun Club	a	int.	24	30	-122.087674	38.154766	Replaced CMP pipe with HDPE pipe (open, no structures)	Infrastructure table
	419	Miramonte	k	Int.	36	30	-122.082825	38.139137	Replaced pipe with open corrugated HDPE pipe (no	Infrastructure table
	424	Lower Joice Island	j	Int.	36	-	-122.062823		Replaced Gate with 36" Stainless Canal Gate (Screw gate)	Infrastructure table
	424	Lower Joice Island	k	Int.	36	_	-122.066801		Replaced Gate with 36" Stainless Canal Gate (Screw gate)	Infrastructure table
	424	Lower Joice Island	u	Int.	36	-	-122.063118		Replaced Gate with 36" Stainless Canal Gate (Screw gate)	Infrastructure table
	424	Lower Joice Island	v	Int.	36	-	-122.063065	38.142059	Replaced Gate with 36" Stainless Canal Gate (Screw gate)	Infrastructure table
	520	Grizzly Ranch	i	Int	24		-121.9844485	38.17783336	Replaced Gate with Stainless Steel canal gate	Infrastructure table
	621	Stone Duck	h	Int	36	30	-121.937505		Replaced CMP pipe with corrugated plastic pipe	Infrastructure table
	631	Meins Landing	A	Ext	36	24	-121.909249	38.138348	Replaced Gate with 36" Canal Gate (Screw gate)	Infrastructure table
	621	Maina I 4:	P	Tet	10	24	121 000440	20.120200	Exterior Open/Replaced Interior Gate with Stainless Steel	Infrastruct 4-1-1
	631 702	Meins Landing MILCO	B +	Int	18 24	24	-121.909449 -122.099125	38.138290 38.124773	Replaced Pump (24" HDPE discharge with flap gate)	Infrastructure table Infrastructure table
	702	Mallard Haven	A	Int.	24	-	-122.099125		Replaced Gate with 24" HDPE discharge with hap gate)	Infrastructure table
	, 00	Transaction of	.,				122.077632	30.100338	Replaced Gates with Ext. 24" Stainless Flap Gate and Int. 24"	
	715	Fleetside Farms	A	both	24	-	-122.087723	38.099430	HDPE FBR	Infrastructure table
	715	Fleetside Farms	Е	Both	36	50	-122.095020		Replaced Gates with Ext./Int. 36" Screw Flap Gates	Infrastructure table
	804	Sprig Farm	j	Interior	30	40	-121.966559	38.106628	Replaced CMP Pipe with HDPE	Infrastructure table
	804	Sprig Farm	k	Interior	30	40	-121.966641		Replaced CMP Pipe with HDPE	Infrastructure table
	804	Sprig Farm	1	Interior	30	40	-121.966372	38.106176	Replaced CMP Pipe with HDPE	Infrastructure table
Installed New Structures	503	Montezuma Duck Club		Ext	16	50	-122.036265	38.169187	NEW drain pump discharge pipe 16" HDPE with SS flap ext.	IMP section B.2, Infrastructure table, NAIP map, & Infrastructure map
	503	Montezuma Duck Club	+		16		-122.036265	38.169187	NEW pump (portable diesel)	Infrastructure table, NAIP map, & Infrastructure map
	504	Gum Tree Farms		Ext	16	40	-122.020657	38.168982	NEW drain pump discharge pipe 16" HDPE with SS flap ext.	IMP section B.2, Infrastructure table, NAIP map, & Infrastructure map
	504	Gum Tree Farms		Ext	16	40	-122.020657	38.168982	NEW drain pump discharge pipe 16" HDPE with SS flap ext.	IMP section B.2, Infrastructure table, NAIP map, & Infrastructure map
	504	Gum Tree Farms	+		12		-122.020657	38.168982	NEW pump (portable diesel) 2 12" discharges	IMP section B.2, Infrastructure table, NAIP map, & Infrastructure map
	514	Tree Slough Farms	k	Ext	36	50	-122.013333	38.173889	NEW drain Gate HDPE pipe SS flap ext/FBR int	Infrastructure table, NAIP map, & Infrastructure map NAIP map,
Moved Existing Structures	408/409	Franciscan Marshview					-122.103434	38.166496	Moved blind #1	Infrastructure map, & LIDAR map NAIP map,
	502	Grizzly Club							Replaced blinds #7 and #8 with 2 man steel tanks	Infrastructure map, & LIDAR map
	302	Grizziy Ciuo							Correction to NAIP & Infrastructure maps - Structure "L" should be labeled as structure "F" (36" exterior Stainless	NAIP &
	133	Shelldrake	L	Ext	36	-			Screw/Flap), Structure "F" should be labeled as "f"	Infrastructure Map
Corrections	413	Sprigateal	a						Correction - Pipe is HDPE	Infrastructure table
to 2021	413	Sprigateal	b						Correction - Pipe is 30"	Infrastructure table
Certified	413	Sprigateal	С						Correction - Pipe is 24"	Infrastructure table
IOAHMP	413	Sprigateal	d	Int					Correction - Interior Gate is Open	Infrastructure table
	413	Sprigateal Sprigateal	e f	Int					Correction - Interior Gate is Open  Correction - Pipe is 18" x 25", Interior Gate is Open, "f" needs to be added to the NAIP and Infrastructure maps	Infrastructure table Infrastructure Table, NAIP & Infrastructure Map
Update in GeoMarsh Only	625	Pintail Ranch Tjuana pond							Replaced blind # 1 in the tjuana pond with 2 man fiberglass	No Changes to IOAHMP
									Club #504 installed a new portable diesel pump with 2-16"	IMP section B.2 &
Update Due	537	West Wind							drain pipes	Infrastructure map
to Shared	619	Schafer Farms							Club #621 replaced structure "h" CMP pipe with CPP	Infrastructure Table
Water	623	Frost Slough							Club #621 replaced structure "h" CMP pipe with CPP	Infrastructure Table
Level/Water Control	625	Pintail Ranch							Club #621 replaced structure "h" CMP pipe with CPP	Infrastructure Table Infrastructure Table
Structures	632	Sheriff Pond Boles Pond							Club #621 replaced structure "h" CMP pipe with CPP Club #621 replaced structure "h" CMP pipe with CPP	Infrastructure Table
Structules	634	Grizzly Hilton							Club #621 replaced structure "h" CMP pipe with CPP  Club #621 replaced structure "h" CMP pipe with CPP	Infrastructure Table
	034	GLIZZIY HIIIOH							Ciao 11021 repiacea su acture 11 Civir pipe with Crr	astracture Table

# **Notice of Exemption**

Appendix E

<b>To:</b> Office of Planning and Research P.O. Box 3044, Room 113 Sacramento, CA 95812-3044	From: (Public Agency):					
County Clerk						
County of:	(Address)					
Project Title:						
Project Location - Specific:						
Project Location - City:	Project Location - County:					
Description of Nature, Purpose and Beneficia						
Name of Public Agency Approving Project: _						
Name of Person or Agency Carrying Out Pro	ject:					
	)(3); 15269(a));					
Reasons why project is exempt:						
Lead Agency Contact Person:	Area Code/Telephone/Extension:					
If filed by applicant:  1. Attach certified document of exemption 2. Has a Notice of Exemption been filed	n finding. by the public agency approving the project? Yes No					
Signature: Manufacture:	Date: Title:					
Signed by Lead Agency Sign	ned by Applicant					
Authority cited: Sections 21083 and 21110, Public Res Reference: Sections 21108, 21152, and 21152.1, Publ						